



Visit and Download Full Version Certificationtime Exam Dumps
<https://certificationtime.com/updated/300-180-exam-dumps-pdf/>



Cisco 300-180 Dumps

DCIT Troubleshooting Cisco Data Center Infrastructure (DCIT) <https://certificationtime.com/>





QUESTION 1

What can prevent you from adding an interface to a pre-existing port-channel on a CISCO Nexus N7K device?

- A. The port-channel is In LACP passive mode
- B. The interface already assigned to a different port-channel,
- C. The interface has been allocated to a different VOC
- D. no shutdown was issued on the interface.

Answer: B

QUESTION 2

You are using the CISCO ACI programmatic features and you receive this error message from the REST API Token Was invalid (Error: Token timeout)

Which option is a possible cause Of the error?

- A. The REST API requires that a login is refreshed
- B. The header or request sent to the web server IS malformed such that the request cannot be parsed by the web server
- C. The HTTP port is disabled on the Cisco APICs and HTTPS is enabled
- D. The CISCO APIC fails to resolve the distinguished name.

Answer: A

QUESTION 3

You are configuring a Cisco Nexus 9000 Series Switch. Which configuration can be implemented for VXLAN BGP EVPN?

- A. VXLAN BGP EVPN by using an NVE interface in a default VRF
- B. RACLs on the Layer 3 uplinks for the VXLAN traffic
- C. QoS classification for the VXLAN traffic on all of the interfaces
- D. DHCP snooping on the VXLAN VLANs

Answer: B

QUESTION 4

Refer to the exhibit.

300-180 dumps exhibit

Your customer is migrating their existing top-of-rack data center to a new location that uses an end-of-rack configuration. The customer requests a site survey prior to the migration.

Which fact must you highlight in your survey that is required for a successful translation?

- A. power source must be 240 volts only for blade chassis.
- B. power source must be 240 volts only for fabric interconnect switches.
- C. blade chassis using passive TWNAX cables must be placed within 5 meters of the end rack.
- D. Blade chassis must not be fully equipped with blades when using and end-of-racksetup.

Answer: C

QUESTION 5

Refer to the exhibit.

300-180 dumps exhibit

You attempt to delete the N7K-1 VDC, the operation is unsuccessful. Which cause of the issue is true?

- A. Custom resource allocations are assigned in the VDC.
- B. N7K-1 is the default VDC.
- C. You are logged in as vdc-admin.
- D. Interfaces are assigned to N7K-1.

Answer: D

QUESTION 6



Which tools can assist in the troubleshooting of FC-0 issues? (Choose three.)

- A. FC analyzer
- B. SPAN
- C. Device Manager
- D. show interface fc1/1 optical-power-budget
- E. PAA
- F. a portable protocol analyzer

Answer: ACF

QUESTION 7

You are no longer seeing updates to the device-aliases database on your Cisco Nexus 5596UP Switch. Which command is useful to determine if the scope of Cisco Fabric Services application distribution was being administratively limited?

- A. N5K2# show cfs region
- B. N5K2# show cfs scope
- C. N5K2# show cfs locale
- D. N5K2# show cfs acl
- E. N5K2# show cfs firewall

Answer: A

Full Access

<https://certificationtime.com/updated/300-180-exam-dumps-pdf/>